MATERIAL SAFETY DATA SHEET

 Section 1 — PRODUCT IDENTI 	FICATION			· · · · · ·		
MANUFACTURER'S NAME DEARRORN CHEMICAL CO. Submidian II D. C						
ADDRESS 300 Genesee St., Lake 2			Grace & Co.		312/	438-8241
CHEMICAL NAME AND SYNONYMS	durich, ri	00047		 -		
Boiler Water Treatment	t ·				E NAME OR CODE DEARBORN® 1	
Section 2 – INGREDIENTS		CAS No. %			EXPOSURE CRITERIA	
					arti odonie (ATTEMA
				-		
Sodium Hydroxide		1310-73-2 100 TLV: 2 mg/m^3 (ceiling)				
			• «			_
•		*	. •	-		
•	•			NFPA 3-0-1		
			·		HELK J-	
 Section 3 — PHYSICAL DATA 						
BOILING POINT, 760mm Hg		N/A	MELTING POIN	T		N/K
SPECIFIC GRAVITY (H20 = 1)	8-9 lbs/ga	al.	VAPOR PRESSU	JRE		N/A
/APOR DENSITY (AIR = 1)		N/A	SOLUBILITY IN H2O, % BY WT.			Appreciable
% VOLATILES BY VOLUME		N/A	EVAPORATION	RATE,	= 1	N/A
APPEARANCE AND ODOR White crystals		h no	pH of a 5% solution		approx. 14.0	
 Section 4 — FIRE AND EXPLOS 	SION HAZAR	D DATA			<u> </u>	
FLASH POINT (and Method Used) Non	e FLA	FLAMMABLE LIMITS in AIR, % by VOLUME AUTO IGNITION TEMPERATURE LOWER N/A UPPER N/A N/A				
EXTINGUISHING MEDIA			□ CO ₂ □ Dry Chemical □ Other			
SPECIAL FIRE FIGHTING PROCEDURE	ES	None				
UNUSUAL FIRE AND EXPLOSION HAZ	ZARD					
			None			
Section 5 - REACTIVITY DATA	<u> </u>					
STABILITY (Normal Conditions)	CONDITIONS TO AVOID					
☐ Stable ☐ Unstable	Avoid leaving open containers. Product will absorb moisture.					
INCOMPATIBILITY (Materials to Avoid)		-		5.5		
	Acids o	r acidio	solutions			
HAZARDOUS DECOMPOSITION PRODU	JCTS					
			None			
AZARDOUS POLYMERIZATION	None					
☐ May Occur ► Will Not Occur						
	-		,		(ove	r)

Section 6 HEALTH HAZARD INFORMA	
EXPOSURE LIMIT	ATTON
Not establis	shed
EFFECTS OF OVEREXPOSURE	
INHALATION	
Avoid breathing dust and lungs.	s which will cause irritation of nasal passages
and rungs.	
or graperruit with water in copious	by giving diluted vinegar, or juice of lemon, orange amounts. Call a physician at once. MAY BE FATAL
IF SWALLOWED.	
SKIN OR EYE CONTACT	
immediately flush with water and right	als; causes skin burns and eye damage. For skin: nse with vinegar, if desired. For eyes: flood with th 5% boric acid solution. CALL PHYSICIAN.
EMERGENCY AND FIRST AID PROCEDURES	·
	See above
 Section 7 — SPECIAL PROTECTION INFO 	RMATION
VENTILATION REQUIREMENTS Mechanical	is suitable for most uses.
	To see and to see and the see
RESPIRATORY PROTECTION (Specify Type)	
has been suggested for similar use.	adequate respirator for dusting - 3M #8710 or equal
EYE PROTECTION	
v	GLOVES (Specify Type)
Face shield or goggles	Rubber gloves
OTHER PROTECTIVE CLOTHING AND EQUIPMENT	「(Specify Type)
None	
Section 8 - SPILL OR LEAK PROCEDURE	
STEPS TO BE TAKEN IF MATERIAL IS RELEASED (
	Take up dry spills and if uncontaminated
return to storage container. Mop an	rea and flush to drain with plenty of water.
control agency. This product IS an I	authorized scavenger service by incineration or use of disposal instructions, contact your state water pollut EPA Hazardous Waste (Corrosive - D002).
Section 9 - SPECIAL PRECAUTIONS	
RECAUTIONS TO BE TAKEN IN HANDLING AND S	Need confamers closed and dry. Profest
from physical damage. Freeze point	of a 10% solution, 14° F.
THER PRECAUTIONS For industrial u	use only. Keep away from reach of children.
hipping Name: DOT Sodium hydroxide,	· · · · · · · · · · · · · · · · · · ·
IATA	Prepared By W. M. Morris
	W. M. MOFFIS
	Date: 7/78 (Revised 6/84)